



LIFT SAFE LIMITED

Unit 16 Hawksley Court
Hawksley Street Industrial
Estate
Oldham, OL8 4PQ

Tel: +44 (0) 161 626 9628
Fax: +44 (0) 161 626 9728
E-Mail: info@liftsafe.net
Web Site: www.liftsafe.net

RAMS

Equip No:	4343	Inspect No:	32714	Site: Fort Kinnaird Customer Services, Management Suite Fleming House Edinburgh EH15 3RD
Make/Model:	ALKE / ATX330E	Job No:	38101	
Serial No:	ZA9ACC32125K87015	Contact:	Sarah Robinson	
Cust Equip No:	MF72 VWD	Inspected:	04/11/2025	
Meter:		Printed:	02/07/2026	
			Page: 1 of 1	

Items to Inspect	Result	Comments
RAMS		
Do I have the correct PPE and equipment for this task?	Not Applicable	N
Do I need help to do this task?	Not Applicable	N
Do I have the required permits (hot works/heights/confined space)?	NO-RAMS	N
Are there are other hazards associated with this task?	YES-RAMS	Y
Can something fall on / strike me or others?	YES-RAMS	Y
Do I have to isolate to control sources of energy?	YES-RAMS	Y
Could this task impact on the environment?	YES-RAMS	Y
Is there a procedure for this task (SOP, SWP, SPL, RA, MS)?	NO-RAMS	N

Service carried out by: Engineer Name: Miles Reynolds

Signature:



Customer Name: Customer Not Present

Signature:



LIFT SAFE LIMITED
Unit 16 Hawksley Court
Hawksley Street Industrial
Estate
Oldham, OL8 4PQ

Tel: +44 (0) 161 626 9628
Fax: +44 (0) 161 626 9728
E-Mail: info@liftsafe.net
Web Site: www.liftsafe.net

2024 Alke/LVT/Cenntro Service

Equip No:	4343	Inspect No:	33057	Site: Fort Kinnaird Customer Services, Management Suite Fleming House Edinburgh EH15 3RD
Make/Model:	ALKE / ATX330E	Job No:	38101	
Serial No:	ZA9ACC32125K87015	Contact:	Sarah Robinson	
Cust Equip No:	MF72 VWD	Inspected:	04/11/2025	
Meter:		Printed:	02/07/2026	
			Page: 1 of 3	

Items to Inspect	Result	Comments
Equipment Info		
Serial Number	Text Field	051
Hours Worked	Text Field	1488
Mileage	Text Field	6887
Equipment Condition		
Body Condition	Good	
Chassis Condition	Good	
Does the machine have any attachments? E.g. cargo box, tow hitch, trailer hook, etc	Text Field	Box
Cab Condition (Interior & Outer)	Good	
Seat Condition	Good	
Check Seatbelt (If Fitted)	Good	
Electrical Info		
Horn Operation	Pass	
Check operation of displays/indicators/controls/instrument cluster	Pass	
Keyswitch/Emergency Stop	Pass	
Fuses/Wiring	Pass	
Exterior/Interior Lights	Pass	
Beacon Operation (If Fitted)	Pass	
Reverse Alarm Operation (If Fitted)	Pass	

Items to Inspect	Result	Comments
Electrical Info		
Motion Alarm Operation (If Fitted)	N/A	N
Check Controller/Scan For Fault Codes (Provide Photo) / Clear Fault History	Pass	
Electric Motor/Motor Brushes/Phase Cables/Connections	Good	
Encoder	Pass	
Contactors	Pass	
Accelerator Pedal/Potentiometer	Pass	
Chassis Info		
Tyre Size	Text Field	N
Remove Wheels & Grease Axles	Pass	
Check Wheel Bolts/Nuts	Pass	
Tyre Condition/Inflation Pressures (Adjust As Necessary)	Poor	
Foam Filled Or Pneumatic	Text Field	P
Brakes		
Check Brake Pad Lining Thickness	Good	
Check/Adjust Brake Fluid Level (To Be Changed Every 2 Years)	Pass	

Service carried out by: Engineer Name: Miles Reynolds

Signature:

Customer Name: Customer Not Present

Signature:



LIFT SAFE LIMITED
Unit 16 Hawksley Court
Hawksley Street Industrial
Estate
Oldham, OL8 4PQ

Tel: +44 (0) 161 626 9628
Fax: +44 (0) 161 626 9728
E-Mail: info@liftsafe.net
Web Site: www.liftsafe.net

2024 Alke/LVT/Cenntro Service

Equip No:	4343	Inspect No:	33057	Site: Fort Kinnaird Customer Services, Management Suite Fleming House Edinburgh EH15 3RD
Make/Model:	ALKE / ATX330E	Job No:	38101	
Serial No:	ZA9ACC32125K87015	Contact:	Sarah Robinson	
Cust Equip No:	MF72 VWD	Inspected:	04/11/2025	
Meter:		Printed:	02/07/2026	
			Page: 2 of 3	

Items to Inspect	Result	Comments
Brakes		
Check Condition Of Braking Circuit	Good	
Remove Brake Drums And Adjust Brake Shoes (Where Necessary)	Pass	
Suspension-Steering		
Check Suspension Linkages, Shock Absorbers And Springs	Poor	
Check Steering System For Condition/Free Play	Good	
Check All Wheel Bearings/Hub Seals	Poor	
Check Differential And Adjust Oil Level (Where Necessary) - Advise Change Every 2 Years	Poor	
Lubricate All Grease Points	Pass	
Batteries		
Check Batteries For Condition/Voltages/SG Readings	Good	
Battery Cabling/Terminal Connector Condition	Good	
Battery Electrolyte Levels (Where Applicable)	N/A	N
Battery Fill Kit (If Fitted)	N/A	N

Items to Inspect	Result	Comments
Batteries		
Battery Display Indicator/Charge Light	Pass	
Battery Charger Condition/Operation	Good	
Operational Test		
Functional Test Of Forward/Reverse Function	Pass	
Functional Test Of Service/Parking Brakes	Pass	
Steering/Wheel Geometry Alignment/Suspension/Tyres/Drivetrain	Pass	
Check Battery Re-Generation	Pass	
Images Videos		
Commentated Walkaround Video Showing The Full Machine And Close Ups Of Any Visible Faults	No	N
4 Images - Front, Back, Both Sides	No	N
Closer Images Of Any Faults/Required Parts	Yes	

Service carried out by: Engineer Name: Miles Reynolds

Signature:

Customer Name: Customer Not Present

Signature:

**LIFT SAFE LIMITED**

Unit 16 Hawksley Court
Hawksley Street Industrial
Estate
Oldham, OL8 4PQ

Tel: +44 (0) 161 626 9628
Fax: +44 (0) 161 626 9728
E-Mail: info@liftsafe.net
Web Site: www.liftsafe.net

2024 Alke/LVT/Cenntro Service

Equip No:	4343	Inspect No:	33057	Site: Fort Kinnaird Customer Services, Management Suite Fleming House Edinburgh EH15 3RD
Make/Model:	ALKE / ATX330E	Job No:	38101	
Serial No:	ZA9ACC32125K87015	Contact:	Sarah Robinson	
Cust Equip No:	MF72 VWD	Inspected:	04/11/2025	
Meter:		Printed:	02/07/2026	
		Page: 3 of 3		

Items to Inspect	Result	Comments
------------------	--------	----------

Recommendations

Front tyres worn. Kenda 225/55×12 on rims.(4 hole)
Replace.
113.878 x2.
N/S rear hub oil seal leaking.
Replace.
113.623. Oilseal.
113.616. Gasket.
Gear oil.
O/S rear suspension unit leaking.
Replace.
100.533.

Service carried out by: Engineer Name: Miles Reynolds

Signature:

Customer Name: Customer Not Present

Signature: